



**VirTower LLC**  
13721 Jetport Commerce Pkwy, Suite 2  
Fort Myers FL 33913  
Phone +1 888 31 70 747  
virtower.com | info@virtower.com

## Snapshot Local Time

Start Date	11/01/2025 00:00 LT
End Date	11/30/2025 23:59 LT

Creation	12/02/2025 09:24
User	KBKX_MATT
Customer ID	KBKX

## Summary

Landings		Take-Offs		Totals	
Single Engine	1233	Single Engine	1247	Single Engine	2480
Single Engine Turbine	7	Single Engine Turbine	8	Single Engine Turbine	15
Multi Engine	230	Multi Engine	253	Multi Engine	483
Multi Engine Turbine	16	Multi Engine Turbine	14	Multi Engine Turbine	30
Business Jet	16	Business Jet	16	Business Jet	32
Jet 2	2	Jet 2	2	Jet 2	4
Helicopter	2	Helicopter	1	Helicopter	3
TOTAL	1506	TOTAL	1541	TOTAL	3047

## FAA AAC/ADG Summary

Landings		Take-Offs		Totals	
A1	1456	A1	1493	A1	2949
A2	5	A2	5	A2	10
B1	4	B1	4	B1	8
B2	27	B2	25	B2	52
C2	1	C2	1	C2	2
C3	2	C3	2	C3	4
D2	2	D2	2	D2	4
HEL	1	HEL	0	HEL	1
UKN	8	UKN	9	UKN	17
TOTAL	1506	TOTAL	1541	TOTAL	3047

### Operations by Aircraft Type

[illegible]

Airport Operations

Snapshot Local Time

Start Date11/01/2025 00:00 LT

End Date11/30/2025 23:59 LT

Creation12/02/2025 09:24

UserKBKX\_MATT

Customer IDKBKX

Single Engine	Single Engine Turbine	Multi Engine	Multi Engine Turbine	Business Jet	Jet 2	Jet NB	Jet 4	Jet WB	Helicopter
C177	2								
C180	4								
C182	16								
C210	2								
GLAS	36								
LANCAIR	2								
M20	3								
P28A	6								
PA22	4								
PA24	3								
PA28	42								
PA32	5								
RV10	2								
Others	8								

Activity Summary

DANA STADIUM	69
FBO RAMP	1134
LAKE CAMPBELL	318
LANDING RWY 12	339
LANDING RWY 17	177
LANDING RWY 30	983
LANDING RWY 35	7
NOISE AREA	224
SELF FUEL	13
TAKEOFF RWY 12	305
TAKEOFF RWY 17	244
TAKEOFF RWY 30	980
TAKEOFF RWY 35	12
TAXIWAY A	1164
TAXIWAY A2	477
TAXIWAY A3	72
TAXIWAY B	798
TAXIWAY C	312
TERMINAL RAMP	567

*This report was generated using sensors monitoring aircraft operations at the selected airport and may not contain aircraft that do not have ADS-B. Airports that have multiple sensors deployed will also feature aircraft fitted with transponders only. The information presented is correct to the best of our knowledge from available sensors at the time: Les Goldsmith, President VirTower LLC*