



Airport Operations Tracking

**VirTower LLC**

13721 Jetport Commerce Pkwy, Suite 2  
 Fort Myers FL 33913  
 Phone +1 888 31 70 747  
 virtower.com | info@virtower.com

Airport Operations

**Snapshot Local Time**

Start Date 07/01/2023 00:00 LT  
 End Date 07/31/2023 23:59 LT

Creation

08/02/2023 13:43

User

KBKX\_MATT

Customer ID

KBKX

**Summary**

Landings		Take-Offs		Totals	
Single Engine	1813	Single Engine	1806	Single Engine	3619
Multi Engine	206	Multi Engine	202	Multi Engine	408
Multi Engine Turbine	3	Multi Engine Turbine	3	Multi Engine Turbine	6
<b>TOTAL</b>	<b>2022</b>	<b>TOTAL</b>	<b>2011</b>	<b>TOTAL</b>	<b>4033</b>

**FAA AAC/ADG Summary**

Landings		Take-Offs		Totals	
A1	2019	A1	2008	A1	4027
B2	3	B2	3	B2	6
<b>TOTAL</b>	<b>2022</b>	<b>TOTAL</b>	<b>2011</b>	<b>TOTAL</b>	<b>4033</b>

**Operations by Aircraft Type**

Single Engine	Single Engine Turbine	Multi Engine	Multi Engine Turbine	Business Jet	Jet 2	Jet NB	Jet 4	Jet WB	Helicopter
7KCAB	2	PA44	408	BE9L	6				
C172	3617								

**Activity Summary**

DANA STADIUM	86
FBO RAMP	860
LAKE CAMPBELL	159
LANDING RWY 12	726
LANDING RWY 17	16
LANDING RWY 30	1279
LANDING RWY 35	1
NOISE AREA	82
SELF FUEL	1
TAKEOFF RWY 12	692
TAKEOFF RWY 17	19



Airport Operations Tracking

**VirTower LLC**

13721 Jetport Commerce Pkwy, Suite 2

Fort Myers FL 33913

Phone +1 888 31 70 747

virtower.com | info@virtower.com

Airport Operations

**Snapshot Local Time**

Start Date 07/01/2023 00:00 LT

End Date 07/31/2023 23:59 LT

Creation

08/02/2023 13:43

User

KBKX\_MATT

Customer ID

KBKX

TAKEOFF RWY 30	1298
TAKEOFF RWY 35	2
TAXIWAY A	906
TAXIWAY A2	401
TAXIWAY A3	50
TAXIWAY B	669
TAXIWAY C	251
TERMINAL RAMP	445
<b>TOTAL</b>	<b>7943</b>

*This report was generated using sensors monitoring aircraft operations at the selected airport and may not contain aircraft that do not have ADS-B. Airports that have multiple sensors deployed will also feature aircraft fitted with transponders only. The information presented is correct to the best of our knowledge from available sensors at the time: Les Goldsmith, President VirTower LLC*