

Figure 1: Historic photo



Figure 2: South Side



Figure 3: West side (storefront)



Figure 4: Close up storefront



Figure 5: Closeup storefront



Figure 6: Storefront



Figure 7: Storefront



Figure 8: storefront





0

6

5

INC

REVERSE

STOP





Figure 9: South side storefront




Figure 10: South





 **pasque**
DECOR + STYLING + GIFTS + MORE

PASQUE
ESTD 2019
REAL LIVING

WHEELCHAIR
ACCESS
ACCESSIBLE
ABSOLUTELY
NO PARKING


PARKING
ONLY







Figure 11: Window revealed under wood siding



Figure 12: South side wood siding removed





Figure 13: Building to the south



Figure 14: Buildings to the west



Figure 15: Buildings to west





Figure 16: south view of building